

Mag Plus Density Probe

Assembly Guide

Notice

Veeder-Root makes no warranty of any kind with regard to this publication, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose.

Veeder-Root shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this publication.

Veeder-Root reserves the right to change system options or features, or the information contained in this publication.

This publication contains proprietary information which is protected by copyright. All rights reserved. No part of this publication may be photocopied, reproduced, or translated to another language without the prior written consent of Veeder-Root.

Contact TLS Systems Technical Support for additional troubleshooting information at 800-323-1799.

DAMAGE CLAIMS / LOST EQUIPMENT

Thoroughly examine all components and units as soon as they are received. If any cartons are damaged or missing, write a complete and detailed description of the damage or shortage on the face of the freight bill. The carrier's agent must verify the inspection and sign the description. Refuse only the damaged product, not the entire shipment.

Veeder-Root must be notified of any damages and/or shortages within 30 days of receipt of the shipment, as stated in our Terms and Conditions.

VEEDER-ROOT'S PREFERRED CARRIER

1. Contact Veeder-Root Customer Service at 800-873-3313 with the specific part numbers and quantities that were missing or received damaged.
2. Fax signed Bill of Lading (BOL) to Veeder-Root Customer Service at 800-234-5350.
3. Veeder-Root will file the claim with the carrier and replace the damaged/missing product at no charge to the customer. Customer Service will work with production facility to have the replacement product shipped as soon as possible.

CUSTOMER'S PREFERRED CARRIER

1. It is the customer's responsibility to file a claim with their carrier.
2. Customer may submit a replacement purchase order. Customer is responsible for all charges and freight associated with replacement order. Customer Service will work with production facility to have the replacement product shipped as soon as possible.
3. If "lost" equipment is delivered at a later date and is not needed, Veeder-Root will allow a Return to Stock without a restocking fee.
4. Veeder-Root will NOT be responsible for any compensation when a customer chooses their own carrier.

RETURN SHIPPING

For the parts return procedure, please follow the appropriate instructions in the "General Returned Goods Policy" pages in the "Policies and Literature" section of the Veeder-Root **North American Environmental Products** price list. Veeder-Root will not accept any return product without a Return Goods Authorization (RGA) number clearly printed on the outside of the package.

Introduction

Important	1
Contractor Certification Requirements	1
Related Manuals	1

Mag Plus Density Probe Installation Kits

Installation Kits	2
-------------------------	---

Assembling Probe Components

Attaching Probe Canister Insulator Sleeves (2-Inch Risers)	4
Attaching Probe Canister Stabilizer Rings (3- & 4-Inch Risers)	4
Assembling Floats onto Probe Shaft	6
Attaching Cable Connector to Probe Canister	6

Figures

Figure 1.	Identifying Mag Plus Density Probe Installation Kit Components	3
Figure 2.	Installing Probe Canister Insulator Sleeves	4
Figure 3.	Installing Probe Canister Spacer Rings	5
Figure 4.	Example Installation of Density Probe Floats and Boot	6

Tables

Table 1.	Installation Kit (with seal kit) - P/N 886002-XXX or P/N 886000-XXX	2
Table 2.	Installation Kit (without seal kit) - P/N 886001-XXX	2
Table 3.	Record of Installed Probe Float and Density Codes by Tank	7

Introduction

This manual describes how to identify and assemble the components of the Mag Plus Density Probes. Instructions are included for assembling floats onto the probe's shaft, attaching spacer rings to the probe's canister, and attaching the probe's cable to the probe.

For guidelines on site preparation, instructions on installing the probe into a tank, and instructions on connecting wiring from the probe to the console, you must refer to the appropriate Veeder-Root Site Preparation and Installation manual.

For setup information, you must refer to the appropriate Veeder-Root Setup manual.

Important

Some of the installation kit components, such as epoxy packs, will be needed when installing the probe into the tank. Do not discard any unused parts.

Make a record of the float size and Density Code that is installed on each probe. The installed float size and Density Code will be required for each probe during system setup.

Contractor Certification Requirements

Veeder-Root requires the following minimum training certifications for contractors who will install and setup the equipment discussed in this manual:

Installer (Level 1) Certification: Contractors holding valid Installer Certification are approved to perform wiring and conduit routing; equipment mounting; probe, sensor and carbon canister vapor polisher installation; wireless equipment installation; tank and line preparation; and line leak detector installation.

ATG Technician (Level 2/3 or 4) Certification: Contractors holding valid ATG Technician Certifications are approved to perform installation checkout, startup, programming and operations training, system tests, troubleshooting and servicing for all Veeder-Root Series Tank Monitoring Systems, including Line Leak Detection. In addition, Contractors with the following sub-certification designations are approved to perform installation checkout, startup, programming, system tests, troubleshooting, service techniques and operations training on the designated system.

- Wireless 2
- Tall Tank

VR Vapor Products Certification: Contractors holding a certification with the following designations are approved to perform installation checkout, startup, programming, system tests, troubleshooting, service techniques and operations training on the designated system.

- ISD – In Station Diagnostics
- PMC – Pressure Management Control
- CCVP - Veeder-Root Vapor Polisher
- Wireless – ISD/PMC Wireless
- A current Veeder-Root Technician Certification is a prerequisite for the VR Vapor Products course.

Warranty Registrations may only be submitted by selected Distributors.

Related Manuals

After assembly, consult the appropriate Site Prep and Installation Manual for your console prior to installing the probe in the tank.

Mag Plus Density Probe Installation Kits

Installation Kits


Available Mag Plus Density Probe installation kits are listed in Table 1 and Table 2. The kit components can be identified in Figure 1.

Table 1. Installation Kit (with seal kit) - P/N 886002-XXX or P/N 886000-XXX

Qty.	Description	Part Number
1	Cable	330272-00X
1	Product Float	331XXX-001
1	Water /Density Float	33311X-00X
1	Boot	333202-001
2	Canister Spacers	332457-001 (2-inch riser),or 331555-001 (3 - 4-inch risers)
1	Cable Seal Kit	330020-121

Table 2. Installation Kit (without seal kit) - P/N 886001-XXX

Qty.	Description	Part Number
1	Cable	330272-00X
1	Product Float	331XXX-001
1	Water /Density Float	33311X-00X
1	Boot	333202-001
2	Canister Spacers	332457-001 (2-inch riser),or 331555-001 (3 - 4-inch risers)



987-1.eps

Figure 1. Identifying Mag Plus Density Probe Installation Kit Components

Assembling Probe Components

Attaching Probe Canister Insulator Sleeves (2-Inch Risers)

1. Open the Probe shipping carton so that you have access to the probe. Also open the installation kit.
2. Install the two canister sleeves onto the probe canister as shown in Figure 2.




Figure 2. Installing Probe Canister Insulator Sleeves

Attaching Probe Canister Stabilizer Rings (3- & 4-Inch Risers)

1. Open the Probe shipping carton so that you have access to the probe. Open the installation kit.
2. Set the adjustable arms of the rings for a 3- or 4-inch riser (see Figure 3) as required. Install the two stabilizer rings onto the probe canister as shown in the figure. Note: you must slide the bottom ring up over the probe shaft and onto the lower end of the canister.




Figure 3. Installing Probe Canister Spacer Rings

Assembling Floats onto Probe Shaft

All sizes of the Product and Water/Density Floats and the Boot are assembled on the probe shaft in the exact sequence and orientation shown in Figure 4.

IMPORTANT! Failure to push the boot as far as possible onto the probe shaft could cause the boot and float(s) to fall into the tank. The boot must be pushed on until it “locks” on the probe shaft.

Handle the probe carefully. Striking or dropping the probe will result in loss of calibration and could cause permanent damage.




Figure 4. Example Installation of Density Probe Floats and Boot

Attaching Cable Connector to Probe Canister

1. Make a record of the float size and Density Code for each probe (you can record float data in Table 3). This information will be needed during console configuration.

NOTE: If the Density Code is not available or is not entered into the console during configuration, the density measured accuracy will default to $\pm 2 \text{ kg/m}^3$.

2. Insert probe into the tank. Attach the existing cable connector to the threaded connector on top of the probe canister and tighten down the integral nut.
3. Save the remaining kit components and refer to the appropriate Site Prep Manual to install the probe in the tank and connect it to the field wiring from the console.
4. Refer to the appropriate console setup instructions to configure the Mag Plus Density Probe.

Table 3. Record of Installed Probe Float and Density Codes by Tank

Tank/Product	Float Size	Density Code
1/		
2/		
3/		
4/		
5/		
6/		
7/		
8/		
9/		
10/		
11/		
12/		
13/		
14/		
15/		
16/		
Example → 4/Diesel	2-inch	B7053686719512

